S How to create edit and email a wof to estimate

Powered by guidde



This guide walks you through the steps to create, edit, and email an estimate using Itsallauto.

Go to localhost:5174



Navigate to view completed Warrant of fitnesses

	>≡ itsallauto.com ♠
	WOF Online
	⊕ Create WOF
	Create WOF C WOF Recheck
1	ଦ୍ View Completed WOF's
	Q View Draft WOF's
	Changelog
	PREVIOUS NEXT
	Changelog - Release October 21th, 2024
	Added Motorcycle Brake Test stop within 30 kph.
	Changed the name of the PDF sent to the estimator from "checksheet" to "WOF."
	Sustomer Photo now uses the same system as taking the gistration photo and starts processing as soon as the photo has been taken.
	Added a section to the summary sheetsheet that shows

02 Click "glenn thorley"

Click on the warrant of fitness you wish to create an estimate for.

×	itsal	lauto.com 🗕	
Comple	ted Wof's		
Q Search			
AL	L INSPECTIONS	RECHECKS N	EEDED(LAST 28 DAYS)
Rego	Unique ID	Name	Date Created ψ
LZJ82	1000206	glenn thorley	10/10/2024
KHS334	1000171	glenn thorley	2/10/2024
KHS334	1000170	glenn thorley	2/10/2024
KHS334	1000169	glenn thorley	2/10/2024
PLK190	1000111	glenn thorley	20/09/2024
KHS334	1000081	glenn thorley	5/09/2024
KHS334	1000079	glenn thorley	5/09/2024
KHS334	1000079R1	glenn thorley	5/09/2024
PJD280	100003	Allan	25/08/2024
KH5334	1000002	glenn thorley	25/08/2024
9.	Ro	ows per page: 10 👻	1–10 of 13 < >



Once viewing the warrant of fitness checksheet you can click the view or create estimate button down the bottom of the page.



04 Switch to "estimator.itsallauto.com"

You will now be viewing the estimate.





You can see each estimate has the name of the estimated part or service and under neath the original reason for rejection that the estimated item is bassed of.____

	≡ itsallauto.com			
	KHS334 Glenn Thorley		Labo Total Part Cost Total	ur 8h 53m i \$1201.73 i \$3356.16
		Add Item		
	Pict top		~ /	V
\searrow	STAGE 1 DIAGNOST	IC x1		
	Labour Cost Total			1h \$225 \$225
	Fixed	ıte		0
	REAR RIGHT WHEEL BEA	ARING x1 ve Play		
	Labour Cost Total		1 \$ \$.h 22m 126.53 493.10
	Markup	ı te r		0
	LF G. VING MIRROR x1 Labour			lh
	Labour			1h \$116.2



You have the option to delete or edit any of the estimated items.





To edit an item click on the pencil icon.

	≡ itsallauto.com		
ĸ	HS334 ienn Thorley	Labour Total Part Cost Total	6h 53m \$860.53 \$2715.21
	Open Inspection		
l	Add Item		
	FRONT BOTH DRIVE SHAFT x2 Front Both Driveshaft: Bent or damaged		
	Labour Cost Total	\$ \$18	2h 311.5 12.95
	Markup		D
	FRONT LEFT INDICATOR BULB x1 Front Left Indicator: Bulb Not Working		
	Labour Cost Total	_	15m \$37 \$37
	Fixed	•	D
	Windowreen: Glazing lacks required marks		



You can see the prefix in this case left front , and the name of the item. both of these can be changed by clicking on them.

Edit Indicator Bulb Comments	-	×
FRONT Indicator Bulb		
Originally: Front Left Indicator: Bulb Not Working		
Fixed	Markup	
\$ 37		
Freight Cost		
Labour Hours		
() Oh 15m		
Quantity		
no 1		
	16 4	\$37 - \$46
q.	Close	



Here you can see you have the option to choose fixed and markup, this will affect how the estimate price is calculated.

	×
FRONT Indicator Bulb	
Fixed	Markup
Freight Cost \$ 0 Labour Hours O 0h 15m	
Countity	
	ı ⊨ ¶ ¹ \$37-\$46
g. °	Close
	Edit Indicator Bulb FRONT Indicator Bulb LEFT Indicator Bulb Fixed Fixed Fixed Country Country 1 Country 1



Here you can change any of the values, such as cost time and quantity.

	Edit Indicator Bulb Comments		•
	LEFT Indicator Bulb		
	Originally: Front Left Indicator: Bulb Not Working		
	Fixed	Markup	
	Min.Rrice		
	\$ 37		
-	S 0		
	_ Labour Hours		
	() Oh 15m		
	Quantity		
	№ 1		
		16 4 1	\$37 - \$46
	0	Close	

11 Click "FixedMarkupMin PriceFreight CostLabour HourshmQuantity+-\$45 - \$56.25"

Here you will see the estimated price adjusting with any changes you make.

×
Edit Indicator Bulb Comments
FRONT LEFT Indicator Bulb
Originally: Front Left Indicator: Bulb Not Working
Fixed Markup
MinRrise
\$ 45
Freight Cost
\$ 0
Labour Hours
() Oh 15m
Quantity
≜ 1
\$45-\$50.25 Close



click here to change to markup

	×
Edit Indicator Bulb Comments	
FRONT Indicator Bulb	
	Markup
\$ 45	
Freight Cost	
O 0h 15m	
Quantity	
	1 1 9 1 \$45 - \$56.25
q.e	Close



once again you have the option to change any of the variables affecting the estimated price.

	Edit Indicator Bulb	8
\ .	FRONT LEFT Indicator Bulb Originally: Front Left Indicator: Bulb Not Working	
	Fixed	Markup
	Min Cost	
	\$ 45	
	\$ 0	
	Markup Percent	
	% 150	
	Labour Hours	
	() Oh 15m	
	\$ 120	
	Quantity	
	1	
	÷	9 ¹ \$163.88 - \$204.84
	a.e	Close



You can close out of the editor by clicking either of these.

Edit Indicator Bulb Comments	
FRONT Indicator Bulb	
Originally: Front Left Indicator: Bulb No	t Working
Fixed	Markup
Min Price \$ 45	
Freight Cost	
\$ 0	
C Oh 15m	
Quantity	
	1 6 9 1 \$45-\$56.25
q. [®]	Close

15 Click "Open Inspection"

If you wish to navigate back to the Warrant of fitness you can use this button.

	itsallauto.com	
KHS334 Glenn The	oriey	Labour 7h 8m Total Part Cost \$868.53 Total \$2723.2 1
	KHS334 Toyota Prius 2011	
•	Glenn Thorley glenn@rennacs.com 0273302825	
	Email Photos	ew Checksheet
	Add Item	
FRON	TBOTH DRIVE SHAFT x2	
Front B	oth Driveshaft: Bent or damaged	
Labou Cost Total	r	2h \$311.5 \$1812.95
Mark	up ié	• • 0
FRON	T LEFT INDICATOR BULB x1	
Fr O	Ondicator: Bulb Not Working	
Labor	r	30m
Cost		\$45

16 Click "View Checksheet"

If you wish to simply view the checksheet click this button.

	itsallauto.com	
KHS334 Glenn Tho	vrley	Labour 7h 8m Total Part Cost \$868.53 Total \$2723.21
	KHS334 Tayota Prius 2011	
•	Gle Thorley gleni, renacs.com 02733. 25	
	Email bs	View Checksheet
(C) •	pen Inspection	
	Add Item	
FRON	TBOTH DRIVE SHAFT x2	
Front Bo	oth Driveshaft: Bent or damaged	
Labou	r	2h
Cost		\$311.5
Torur	_	\$1012.75
Mark	up 11	• • 0
FRON	T LEFT INDICATOR BULB x1	
Fr C	Ondicator: Bulb Not Working	
Labou	2	30m
Cost		\$45 .



Click on the designated area.

from and of the boot of the end for	et	instant v	NOF Repair E	stimates		Read	f Brak	ie Test		
ID: 1000170		itsallauto.com			Service Brake Reading(Not Trailers 2000kg or less)					
specting Company Details		Under Bonnel	t Inspection			95		-	Left	Right
iame: itsa	llauto	U1. AF System	Working Order:		F.	63	Or	Front		-
ddress: 998 Heaphy 1	errace	U2. AF Certific	ate Carert		F	L	-	Brain Berlor	Dation .	Let a
		U3. AF System	n Safe:		F	89.4	anin	Brake Perior		
athority Number: N	1:3600	U4. Modified V	/ehicle:		F.	R3. Parking Brake Reading:				
hone: 07 65	5 2037	US. Chassis V	N Number		r.	H	49.0	Darkina	Lint	TROM
mai: admin@itsalaut	lo.com	U6. Structure i	Cerrosien:		F	96	~	Brake	Len.	ingen.
ustomer Details		U7. Engine Dri	ive Tablec	P	×		or	Reading		
ame: gienn t	horley	US. Fuel Syste	m	\square	F	Or Backing Brake Stall Test			-	
ddress: 337 Jary road, rd1 O	haupo	External inspection			Parking Brake Stall Test:					
rdi o	naupo	E1. Direction I	indicator Lamps (Front): 🖌	F	H4, 1	arkers	g Brake Perior	mance	
here: 02733	02825	E2. Forward Fi	acing Position La	mps: 🗹	F	ma i	-aniti	cereand/say be	me.	
mail: glenn@rennai	s.com	E3. Head Lam	pa		F		geeco	antear.		(V)
ehicle Details		E4. Front And	Rear Fog Lamps:		F	Initial Inspection Details				
take: Toyota Model:	Prius	ES. Direction I	indicator Lamps (Rear): P	×	Center	e estip	ecrece Passec		eshobes.
ear: 2011 Rego Plate: K	H5334	E6. Rearward	Facing Position L	amps: 🗸	F	0.400	o n	operands:		Close Thoda
ear First Registered NZ: (01/2017	E7. Stop Lang	96:		F	orgn inno	en.re	in maperior.		Critical Critical
N 7A10H637X17	EE. High Mour	nted Stop Lamps		1	Citza					
dometer:	E9. Registratio	in Plate Lamps:		F	Recheck Inspection Details					
uel Type:	E10. Rear Refi	ectors:		<u>F</u>	Date of Recheck:					
or opry oak:	E11. Other Lan	mps:		빌	Inspector Number:					
OF Details	E 12. Wind Scr	aet:	Lb.	×	Rechark Inspection Dassed					
on/ Lax myoice Namber:	E 13. Other Gla	erg		열	Recheck Inspection Passed					
ST Number:	E14. Doors Ar	d Hinged Panels:	· M		Coornesse.					
ompany Authority Number: N	E 13. MUS Qua	and and here a		븱	Beason for Rejection					
ew wor Expiry Date:	E 10. External	Anter Cod		븱	Fear	Lah	indicator P-R	Not Workie	900	
yttem Authorization Number:	E17. Poofrests	s paretar Cycles O	my; =		Windscreen: Glazino Jacks required marks					
WOF Label Number:		E10 Dimension	NUMPORIOR:		읡	Airbag Light stays on				
structions	_	E 19. Danerisc	710.	<u></u>		Rear	Right	Wheel Bearin	g: Excessive	Play
or Approache		Chassis Unde	rbody Inspectio	n						
um Parend	븕취	C1. Wheels, H	ubs and Axles:	<u></u>	<u>×</u>					
descel becaution		C2. Othering N	PECHANISH:		븱					
Wpers/Operation:	ME	C.J. Eval Track	Frei Lines		믬					
Washers/Operation:	C4. Fuel Tank Fuel Lines			븱						
Rear View Mimors:	C5. Brake Components:			딁						
. Sun Visors:	C6. Exhaust System & Visible Smoke:			딁						
15. Seatbelts & Anchorages:		Cf. Tree constront		-						
6. Seats & Seat Anchorages:		CS. mead And Depth:		-						
. Head Restraints:	T F	Front	2	2	-					
. interior impact:	লিন	Middle								
AirBag Self Check(Dash Light):	PX	Rear	2	2	1					
0. ABS Self Check(Dash Light)	जिन	C9. Toxing Co	meetions:		F	Com	ment	8		
1. Audible Warning Device:	TE	C10. Safety Ci	hain:	-	-					
2. Spare Wheel Security	C11. Dual Safety Chairc ==		-							
1		Cit. Type Cond Cit. Type Cond Cit. Type Cond Cit. Tread Ared Tread (mm) Front Middle Rear Cit. Safety Cit. Cit. Safety Cit. Cit. Safety Cit. Cit. Safety Cit. Cit. Safety Cit.	Itor: Deptk Left 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Roght 2 2 		Corr	ment	5		



here you can view any photos related to the warrant of fitness.

≡ itsallauto.com	
KHS334 Glenn Thorley	Labour 7h 8m Total Part Cost \$868.53 Total \$2723.21
KHS334 Toyota Prius 2011	
Glenn Thorley glenn@rennacs.com 0273302825	
C ² Open Inspection	View Checksheet
Add Item	
FRONT BOTH DRIVE SHAFT x2	
Front Both Driveshaft: Bent or damaged	
Labour	2h
Cost Total	\$311.5 \$1812.95
Markup	• / 🚺
FRONT LEFT INDICATOR BULB x1	
Fry Gendicator: Bulb Not Working	
Cost	30m \$45



To create the email to send to the customer click the email button here.

	itsallauto.com	
KHS334 Glenn Tho	rley	Labour 7h 8m Total Part Cost \$868.53 Total \$2723.21
	KHS334 Tayota Prius 2011	
•	Glenn Thorley glenn@rennocs.com 0273302825	
✓	Email Provide American Comparison	View Checksheet
	Add Item	
FRONT	BOTH DRIVE SHAFT x2	
Front Bo	th Driveshaft: Bent or damaged	
Labour Cost Total		2h \$311.5 \$1812.95
Marke	P 16	• 🗸 🚺
FRONT	LEFT INDICATOR BULB x1	
Labour	2	30m
COST		945 ·



This dropdown list lets you change the template email.



Make any required adjustments to the email.

	C. March. Estimate for VHCZZA 2011 Touche Brive /14 Oct 2004)
	To glenn@rennacs.com X Add recipients
	Send >
	WOF Comments / For Your Assistance: No comments.
	** WOF Comments Total:** \$0
	Please note, any WOF Comments are recommendations and they are not required to pass your WOF.
	WOF Rejections and WOF Comments Total: \$2723.21 incl. GST
	We look forward to hearing from you on how you would like to proceed.
	Thanks
	l itsallauto
	998 Heaphy Terrace
	Fairfield
	Hamilton
	admin@itsallauto.com
	07 855 2037
	KE Charkeheat PDE
l	checksheet_1000170.pdf 327.24 KB



You can now send the email.





Close out the of the email.



24 Click "Open Inspection"

Click this link If you wish you can navigate back to the warrant of fitness system.

	itsallauto.com	
KHS334 Glenn Thorl	ley	Labour 7h 8m Total Part Cost \$868.53 Total \$2723.21
	IHS334 Oyota Prius 2011	
	Flenn Thorley Jenn⊛rennacs.com 1273302825	
C 00	en Inspection	ew Checksheet
	Add Item	
FRONT Front Both	BOTH DRIVE SHAFT x2	
Labour Cost Total		2h \$311.5 \$1812.95
Marku		• • 0
FRONT	LEFT INDICATOR BULB x1	
Labour Cost		30m \$45

Thank you for watching. If you wish to contact us you can email us at admin@itsallauto.com , or phone 07 595 0032

If you know someone who could benefit from our FREE online Warrant of Fitness system, then please let them know about itsallauto.com.

Powered by guidde